Loar Farm
AL-VI-B-241
Barbers Hill Road, east of MD Rte 55
Frostburg vicinity
Allegany County
Katherine Grandine
September 2008

#### **ADDENDUM**

The MIHP form prepared in 1982 documented a log house, a frame bank barn, a double-pen log barn, and root cellar on this farm. A site visit on 16 September 2008 by Mr. Asa Maust of CME Engineering LLC of Frostburg revealed that the farmstead buildings are no longer extant. A new house is under construction at the location.

A strip mine permit was issued for this area during the 1980s (Bill Llewellyn, CME Engineering, LLC, personal communication, 5 September 2008). A desk top study of aerial photographs on Google Earth also confirmed that no buildings survive in the mapped location. The attached illustrations were supplied by CME Engineering LLC.






Figure 1. Rubble at mapped location of AL-VI-B-241 (CME Engineering LLC 9/2008).



Figure 2. View from mapped location of AL-VI-B-241, looking east (CME Engineering LLC 9/2008).



Figure 3. View from mapped location of AL-VI-B-241 looking north showing new house under construction (CME Engineering LLC 9/2008).



Figure 4. View from mapped location of AL-VI-B-241 looking west (CME Engineering LLC 9/2008).

AL-VI-B-241

Loar Farm Loarville Private Late 19th century

This is a story-and-a-half, three bay by one bay log structure with a gable roof.

The house rests on a low, random ashlar/rubble foundation. Weatherboard siding covers the log exterior except where it has fallen off exposing the v-notched logs.

A frame bank barn, a double-pen log barn, and a stone and frame banked root cellar are also located on this farm.

# MARYLAND HISTORICAL TRUST MAGI #0112185635

## INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 1	NAME					
н	ISTORIC					
A	ND/OR COMMON					
ır I	Farm					
I	OCATION					
_	TREET & NUMBER					
	Barbers Hill	Rd. Approx. 1 miles	past end of Montel	Rd. off Rt. 55		
С		mi implicat i miles			СТ	
_	Loarville		VICINITY OF 6t	:h.		
S	Maryland		COUNTY Allegany County			
	CLASSIFICA	ATION				
	CATEGORY	OWNERSHIP	STATUS	PRESI	ENT USE	
8	DISTRICT	PUBLIC	_OCCUPIED	AGRICULTURE	MUSEUM	
7	∠BUILDING(S)	<b>∠</b> RRIVATE	XUNOCCUPIED	COMMERCIAL	PARK	
	_STRUCTURE	вотн	WORK IN PROGRESS	EDUCATIONAL	PRIVATE RESIDEN	
	_SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS	
	_OBJECT	IN PROCESS	_YES: RESTRICTED	GOVERNMENT	_SCIENTIFIC	
		BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	_TRANSPORTATIO	
			<b>≯</b> NO	_MILITARY /	COTHERUACAV	
	IAME	PROPERTY	T	elephone #:	2 51	
S	TREET & NUMBER	. * Decision	× 30 × c a	w n ee a teach		
C	ITY, TOWN			STATE , Z	ip code	
			VICINITY OF			
I	LOCATION	OF LEGAL DESCR	IPTION L	iber #:		
C	OURTHOUSE.		F	olio #:		
R	REGISTRY OF DEEDS, E	TC. Allegany County C	ourthouse			
S	TREET & NUMBER					
		30 Washington Str	eet			
C	ITY, TOWN		3.5	STATE		
		Cumberland		Maryland	21502	
F	REPRESEN'	TATION IN EXIST	ING SURVEYS			
-	ITLE					
T		None				
T						
	ATE					
	ATE		FEDERALST	ATE _COUNTY _LOCAL		
D	EPOSITORY FOR	•	FEDERALST	ATE _COUNTY _LOCAL		
D D S	EPOSITORY FOR		FEDERALST	STATECOUNTYLOCAL		

CONDITION

CHECK ONE

**CHECK ONE** 

\_\_EXCELLENT

DETERIORATED

\_ALTERED

X.ORIGINAL SITE

\_\_GOOD \_\_FAIR \_\_RUINS
\_\_UNEXPOSED

\_MOVED DATE\_\_\_\_

#### DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This abandoned log farm house is situated in a hilly, wooded area on Barbers Hill Road approximately one mile past the dead end of Montel Road. (which is off Rt. 55). The house faces south. It is a story-and -a-half, three bay by one bay log structure with a gable roof. A shed roofed addition runs along the rear, north elevation. A wooden porch supported by plain wood posts is located at the west elevation of the addition. The vertical board central facade door, painted to look like a four panel door, is covered by a wooden, gable roofed porch.

The house has a central brick chimney. The windows are broken out but there is evidence of six over six sash windows. The house rests on a low random ashlar/rubble foundation. Weatherboard siding covers the log exterior except where it has fallen off exposing the v-notched logs. Corrugated metal covers the roof.

On the inside there are two rooms on each floor. The log walls and chinking have been left exposed in the first story east room. In the west room a narrow boxed stairway leads to the second story.

A well is located to the east. A stone and frame root cellar is located northeast of the house. A hewn frame bank barn on a fine ashlar foundation is located also to the northeast. A banked, double pen, saddle notched log barn on a stone foundation is located southeast of the house.

### 8 SIGNIFICANCE

AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW					
_ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION		
_ARCHEOLOGY-HISTORIC	CONSERVATION	LAW	_SCIENCE		
AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE		
<b>X</b> ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN		
ART	ENGINEERING	MUSIC	THEATER		
COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION		
COMMUNICATIONS	_INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)		
	INVENTION				
	_ARCHEOLOGY-PREHISTORIC _ARCHEOLOGY-HISTORIC _AGRICULTURE _ARCHITECTURE _ART _COMMERCE	_ARCHEOLOGY-PREHISTORIC _COMMUNITY PLANNING  _ARCHEOLOGY-HISTORIC _CONSERVATION  _AGRICULTURE _ECONOMICS  _ARCHITECTURE _EDUCATION  _ART _ENGINEERING  _COMMERCE _EXPLORATION/SETTLEMENT  _COMMUNICATIONS _INDUSTRY	_ARCHEOLOGY-PREHISTORIC _COMMUNITY PLANNING _LANDSCAPE ARCHITECTURE _ARCHEOLOGY-HISTORIC _CONSERVATION _LAW _AGRICULTURE _ECONOMICS _LITERATURE _ARCHITECTURE _EDUCATION _MILITARY _ART _ENGINEERING _MUSIC _COMMERCE _EXPLORATION/SETTLEMENT _PHILOSOPHY _COMMUNICATIONS _INDUSTRY _POLITICS/GOVERNMENT		

SPECIFIC DATES

BUILDER/ARCHITECT

#### STATEMENT OF SIGNIFICANCE

This house is a common western Maryland type. Houses of this general rectangular configuration constructed of logs covered with weatherboard siding were built in Allegany County through the nineteenth century.

The buildings on this property display several significant construction features. The log barn is a good example of such structures built in the late 19th century.

The dwelling is a good example of a simple log farmhouse. The painted panels on the batten door indicate an attempt to upgrade a simple vernacular feature to a more stylish level.

The root cellar includes the unique combination of stone nogging over its wooden-framed ceiling. This is reminiscent of "double-floors" constructed between cellars and first floor levels of late 18th and early 19th century dwellings in Western Maryland, particularly those structures built over a spring. The Hager House in Hagerstown (WA- ) and the Superintendent's House in Eckhart (AL-V-A-018 : demolished 1981) utilized such floors.

Maryland 21401

### 9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF	NECESSARY		
10 GEOGRAPHICAL DATA			
ACREAGE OF NOMINATED PROPERTY			
ACREAGE OF NOMINATED PROPERTY	-		
VERBAL BOUNDARY DESCRIPTION			_
		₩F.	
		Fa tower	
A contract of the			
LIST ALL STATES AND COUNTIES FOR PRO	OPERTIES OVERLAPPING S	TATE OR COUNTY BOUNDARIES	
			1
STATE	COUNTY		
	Property of the Control of the Contr		_
STATE	COUNTY		
11 FORM PREPARED BY			
NAME/TITLE Significance: Merry Stinson	_		
David A. Dorsey, Historic S.	n ites Surveyer		
ORGANIZATION	ites buiveyor	DATE	
Maryland Historical Trust/Bu	reau of Mines	May 1982	
STREET & NUMBER		TELEPHONE	
21 State Circle, Shaw Street		(301) 269-2438	
CITY OR TOWN	A114**	STATE	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


RETURN TO: Maryland Historical Trust

Annapolis

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438



Lonaconing, MD-WV USGS 7.5 Minute Series Scale 1:24,000 1950, photorevised 1974

AL-VI-B-241 Loar Farm Barbers Hill Road, approx. 1 mile past end of Montel Road off Rt. 55



AL-VI-B-241
Loar Farm
Allegany Co., MD
D.A. Dorsey 1981
Farmhouse, east elevation




AL-VI-B-241
Loar Farm
Allegany Co., MD
D.A. Dorsey 1981
Farmhouse, east elevation



AL-VI-B-241
Loar Farm
Allegany Co., MD
D.A. Dorsey 1981
Farmhouse; detail; corner



AL-VI-B-241 Loar Farm Allegany Co., MD Dave Dorsey 1981 stairway



AL-VI-B-241
Loar Farm
Allegany Co., MD
D.A. Dorsey 1981
farmhouse, detail; door;



AL-VI-B-241
Loar Farm
Allegany Co., MD
D.A. Dorsey 1981
Log Barn: north elevation



AL-VI-B-241 Loar Farm Allegany Co., MD D.A. Dorsey 1981 Barn; w elevation



AL-VI-B-241 Loar Farm Allegany Co., MD D.A. Dorsey 1981 Detail: log barn



AL-VI-B-241 Loar Farm Allegany Co., MD D.A. Dorsey 1981 Barn; W elevation



AL-VI-B-241 Loar Farm Allegany Co., MD D.A.Dorsey 1981 Frame barn, north elevation